


Lake Erie









Blasting Through BUIs on the Burning River

3 Beneficial Use Impairments Removed




BUI 11 Degradation of Aesthetics REMOVED in 2017



Restrictions on Fish Consumption



7 BUIs Remaining




BUI 3 **Degradation of Fish Populations**



BUI 6 **Degradation of Benthos**





Fish Tumors or Other Deformities



BUI 8 Eutrophication or Undesirable Algae



BUI 7 Restrictions on Navigational Dredging



Assessment Units



miles of river mainstem





square miles of watershed



tributary subwatersheds





(HUC12 subwatersheds)










municipalities





Focusing on Aquatic Life Management Actions


Remove barriers to fish passage


- Gorge and Canal Diversion Dam removals
- Multiple small dam removals

Restore/Create habitat & reconnect floodplain


- 12 Key Projects
- 10 Supplemental Projects











Behind-the-Bulkhead fish habitat on the Cuyahoga River ship channel - Center St. Bridge and Scranton Peninsula